

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AZ260
SSE
1/4-1/2
0.379 mi.
2003 ft.

CONCRETE
2951 WEST 8TH
BROOKLYN, NY

Site 3 of 4 in cluster AZ

NY Spills S122478892
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: CONCRETE
Address: 2951 WEST 8TH
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1801956 / 2018-05-24
Facility ID: 1801956
Facility Type: ER
DER Facility ID: 523718
Site ID: 570507
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2018-05-19
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2018-05-19
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2018-05-19
Spill Record Last Update: 2018-05-24
Spiller Name: LT THOMAS
Spiller Company: UNKNOWN
Spiller Address: 2951 WEST 8TH
Spiller Company: 999
Contact Name: LT THOMAS
DEC Memo: "5/24/18 TJD FDNY responded to location and contained and cleaned 5

gallons of diesel fuel from affected impervious surfaces. No drains
affected. No further action required. Spill closed."
"over fill of vehicle clean up is on going"

Remarks:

All Materials:

Site ID: 570507
Operable Unit ID: 1318347
Operable Unit: 01
Material ID: 2326286
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported